

**Exhibit A**


**Summary of findings and maps**


<b>Ramps</b>	<b>Locations</b>
Ramp running slope > 8.3%	326
Ramp cross slope > 2%	63
Landing < 4'x4'	161
Running/Counter slopes > 11%	172
Counter slope > 5%	4
Grade breaks not flush	234
No detectable warning surface	473
Non-compliant detectable warning surface	11
No Ramp	82
Ramp width < 4'	153
Landing slope > 2%	76
Needs 2nd ramp	42
Parallel ramp & flange running slope > 8.3%	3
Gratings > 1/2"	11
Bumps/trip hazard	5
Protruding object	4
Broken/crack or in disrepair	9
<b>Total</b>	<b>1,829</b>


<b>Sidewalks</b>	<b>Locations</b>	<b>Length</b>
Sidewalk broken/cracked or in disrepair	389	6,439
Protruding object	299	10,572
Cross slope > 2%	3,223	107,188
Width < 4'	78	2,679
Width < 5' & 5' passing zone not w/in 200'	-	-
Gratings > 1/2"	5	28
Surface is not slip resistant	14	1,291
Bumps/trip hazards	795	5,695
No sidewalk	307	150,545
<b>Total</b>	<b>5,110</b>	<b>284,437</b>

<b>Driveways</b>	Locations	Length
Lack of sidewalk in driveway	489	11,677
Cross slope > 2%	648	12,995
Ramp running slope is included & > 8.3%	93	863
Broken/cracked or in disrepair	1	9
Trip hazard present on driveway	21	-
Protruding object	1	-
Total	1,253	25,544

<b>Crosswalks</b>	Locations	Length
Crosswalk width < 4'	-	-
Stop-controlled & cross slope > 2%	95	3,525
Not stop-controlled & cross slope > 5%	5	109
Running slope > 5%	137	3,951
No crosswalk	450	19,306
Striping faded	21	394
Total	708	27,285







# Legend

## Sidewalks

- S1 Sidewalk Broken, Cracked, Disrepair
- S2 Protruding Object
- S3 Cross Slope is > 2%
- S4 Width is < 4 ft.
- S6 Gratings > 1/2 inch
- S7 Surface is Not Slip Resistant
- S8 Bumps/Trip Hazard
- S9 No Sidewalk

Scale: 0 0.25 0.5 Miles



